



Property Inspection Report

Prepared by Leak Detector Sydney

Contents

- | | |
|-------------------------|--------|
| 1. Leak Location Report | Page 2 |
| 2. Roof Report | Page 3 |

Leak Detector Sydney

info@leakdetectorsydney.com.au | <https://leakdetectorsydney.com.au/>

Sydney NSW 2000, Australia

Leak Location

REPORT DETAILS

Property Address:	Maroubra NSW 2035, Australia
Claim/Job No:	1943896
Client Name:	CRD
Person present during the inspection	NA
Inspection Date:	11-11-2025
Type of inspection	Leak Location
Construction Type:	Brick Veneer
Height	Two Storey
Roof Type:	NA
Event or maintenance-related	Maintenance
Roof Pitch	◦
Front photo of Property	



Roof Report

REPORT DETAILS

Property Address:	Sydney, NSW, Australia
Claim/Job No:	
Client Name:	
Person present during the inspection	Ellen Stuart
Inspection Date:	21-05-2024
Type of inspection	Roof Report
Construction Type:	Brick home
Height	Three Storey
Roof Type:	Cement Tiles
Event or maintenance-related	Maintenance
Roof Pitch	21.3°
Front photo of Property	